





Mount International Ultrasound Services Ltd




Transducer Evaluation Report

Manufacturer: Acuson	Customer: Customer	Contact: Contact	
Probe Model: C544	Address: Address		
Serial Number:	City: City	State: CO	Zip Code: Zip
Test Date: 07/03/2006 11:01	Phone Number: Phone		
Test ID: 67	Operator: Alan Preece	Fax Number: Fax	
Purpose: Test Type	DX/Comments:		





Transducer Evaluation Report





Transducer Evaluation Report

Page 3 of 5

Mean: 0.581

Max: 0.640



Min: 0.500

Std Dev: 0.029





Transducer Evaluation Report



First Element Number: 32



Middle Element Number: 64



Last Element Number: 96





Transducer Evaluation Report

Page 5 of 5